


Wlan Report

Top



Report Info

Report created:2026-06-08T13:18:48Z
Report duration:3 days

General System Info

ComputerName: HPC
System Manufacturer:ASUSTeK COMPUTER INC.
System Product Name:Q670EA-IM-A
BIOS Date:10/27/2025
BIOS Version:3.04.00
OS Build:26100.1.amd64fre.ge_release.240331-1435
Machine Id: {FD106C16-D7F7-49DC-834E-D4750FC38A26}
MDM joined: False

User Info

Username: Administrator
User Domain:HPC
User DNS Domain:Unknown

Network Adapters

Device: Mellanox ConnectX-4 Lx Ethernet Adapter #2
PNP ID: PCI\VEN_15B3&DEV_1015&SUBSYS_000315B3&REV_00\4&1F97FB6&0&0008
Guid: {C563E8FF-2CF6-4492-934C-13778B06CF1F}
Current driver version: 26.1.27016.0
Driver date: 1-11-2026
DevNode flags: 0x180200a

Device: Mellanox ConnectX-4 Lx Ethernet Adapter
PNP ID: PCI\VEN_15B3&DEV_1015&SUBSYS_000315B3&REV_00\4&1F97FB6&0&0108
Guid: {412C6DD5-8873-41C8-BB55-39980E391A48}
Current driver version: 26.1.27016.0
Driver date: 1-11-2026
DevNode flags: 0x180200a

Device: Intel(R) I210 Gigabit Network Connection #2

PNP ID: PCI\VEN_8086&DEV_157B&SUBSYS_00008086&REV_03\6&3276C229&0&001800DC

Guid: {40A4F091-57A6-4FFA-B583-758BDA1702F3}

Current driver version: 12.12.226.0

Driver date: 5-4-2015

DevNode flags: 0x180200a

Top

Device: Intel(R) I210 Gigabit Network Connection

PNP ID: PCI\VEN_8086&DEV_1533&SUBSYS_85571043&REV_03\4&27A64FD0&0&00E3

Guid: {3DC650FF-DDA7-40CB-AA6F-7634C83D60D1}

Current driver version: 12.12.226.0

Driver date: 5-4-2015

DevNode flags: 0x180200a

Device: Microsoft Kernel Debug Network Adapter

PNP ID: ROOT\KDNIC\0000

Guid: {072D12E3-F4A1-4A0D-8B0D-2914B5F97E64}

Current driver version: 10.0.26100.8457

Driver date: 6-21-2006

DevNode flags: 0x4180200b

Device: Intel(R) I210 Gigabit Network Connection #3

PNP ID: PCI\VEN_8086&DEV_157B&SUBSYS_00008086&REV_03\6&32C44A6A&0&002000DC

Guid: {15E55359-63B5-4270-A631-D7F14BB5E3A5}

Current driver version: 12.12.226.0

Driver date: 5-4-2015

DevNode flags: 0x180200a

Device: Intel(R) Ethernet Controller I226-LM

PNP ID: PCI\VEN_8086&DEV_125B&SUBSYS_886A1043&REV_04\4&3B8C8D29&0&00E1

Guid: {F06F0F29-4356-4FF0-AE3C-B8E82E65DC9C}

Current driver version: 2.1.5.7

Driver date: 9-3-2025

DevNode flags: 0x180200a

Device: Intel(R) I210 Gigabit Network Connection #4

PNP ID: PCI\VEN_8086&DEV_157B&SUBSYS_00008086&REV_03\6&BFBA6D8&0&001000DC

Guid: {2E17057C-11FD-451E-A7BF-556768259DB5}

Current driver version: 12.12.226.0

Driver date: 5-4-2015

DevNode flags: 0x180200a

Device: Intel(R) I210 Gigabit Network Connection #5

PNP ID: PCI\VEN_8086&DEV_157B&SUBSYS_00008086&REV_03\6&1793B887&0&000800DC

Guid: {5341CE82-9770-4444-9C1D-54F1A065C61A}

Current driver version: 12.12.226.0

Driver date: 5-4-2015

DevNode flags: 0x180200a

Device: Realtek 8832CU Wireless LAN WiFi 6 USB NIC

PNP ID: USB\VID_0BDA&PID_C832\00E04C000001

Guid: {B668AC45-C78E-443B-8549-05FDBFD76294}

Current driver version: 5001.19.113.3

Driver date: 12-17-2024

DevNode flags: 0x180600a

Device: Microsoft Wi-Fi Direct Virtual Adapter #3

PNP ID: {5D624F94-8850-40C3-A3FA-A4FD2080BAF3}\VWIFIMP_WFD\6&2CEB37D7&0&13

Guid: {20682A51-11A8-4D14-B8B7-9C82C71EC32F}

Current driver version: 10.0.26100.8328

Driver date: 6-21-2006

DevNode flags: 0x4180200a

Device: Microsoft Wi-Fi Direct Virtual Adapter #4


PNP ID: {5D624F94-8850-40C3-A3FA-A4FD2080BAF3}\VWIFIMP_WFD\6&2CEB37D7&0&14

Guid: {ECDE0882-F0FD-4AB6-BD25-C87907CC24D9}

Current driver version: 10.0.26100.8328

Driver date: 6-21-2006

DevNode flags: 0x4180200a



Profile Output

```
<!--Interface: Wi-Fi 2, Profile: 시냅스이미징-->

<?xml version="1.0"?><WLANProfile
xmlns="http://www.microsoft.com/networking/WLAN/profile/v1"><name>시냅스이미징</name>
<SSIDConfig><SSID><hex>EC8B9CEB8385EC8AA4EC9DB4EBAFB8ECA795</hex><name>시냅스이미징</name>
</SSID></SSIDConfig><connectionType>ESS</connectionType><connectionMode>auto</connectionMode>
<MSM><security><authEncryption><authentication>WPA3SAE</authentication>
<encryption>AES</encryption><useOneX>false</useOneX><transitionMode
xmlns="http://www.microsoft.com/networking/WLAN/profile/v4">true</transitionMode>
</authEncryption><sharedKey><keyType>passPhrase</keyType><protected>true</protected>
<keyMaterial>01000000008C9DDF0115D1118C7A00C04FC297EB010000007B771A6DD84F5347A9A194B26007F236
000000000200000000001066000000010000200000002F274260746FA15330F5540023753E363DAF2A12568F9D8B8
2969176BB9B11ED0000000000E8000000002000020000000F1AF225581B0BBA6EC37287C7BD607DD29FFCC48BED4AE
81C0A6AFAA6B8C81212000000060C3B1D2B357003654F4C3F4D6FA9B137EAB1F7154C92E5C81D95DD60518C0C1400
0000007594FB08FFE292450C484631E2468A89FC54815175DA4460FD25F69B1C2AD236C59848332C25EDE6A147C5A
AC5908AE13C0C00CB3906D433A9864A762699F05</keyMaterial></sharedKey></security></MSM>
<MacRandomization xmlns="http://www.microsoft.com/networking/WLAN/profile/v3">
<enableRandomization>false</enableRandomization></MacRandomization></WLANProfile>
```

Summary


Session Success/Failures

Status	Count
Successes	0
Failures	1
Warnings	3

Disconnect Reasons

Reason	Count
드라이버에 의해 네트워크 연결이 끊어졌습니다.	4

Session Durations



Top

000000

0 - 1 minutes1 - 5 minutes5 - 10 minutes10 - 30 minutes30 - 60 minutes60 - 360 minutes360+ minutes

Wireless Sessions

Interface:Realtek 8832CU Wireless LAN WiFi 6 USB NIC

Interface GUID: b668ac45-c78e-443b-8549-05fdbfd76294

Connection Mode:프로필에 자동 연결

Profile:시냅스이미징

SSID:시냅스이미징

BSS Type:Infrastructure

Session Duration: 0 hours 0 minutes 0 seconds

Disconnect Reason:드라이버에 의해 네트워크 연결이 끊어졌습니다.

EventId	Time	Message
11004	2026-06-06T10:04:11	[+]무선 보안이 중지되었습니다.
8003	2026-06-06T10:04:11	[+]WLAN AutoConfig 서비스가 무선 네트워크에서 연결이 끊어졌습니다.
1010	2026-06-06T10:04:11	[+]CDE에서 L2 어댑터 제거 보고
10000	2026-06-06T10:04:13	[+]WLAN 확장성 모듈을 시작하지 못했습니다.
1009	2026-06-06T10:04:13	[+]CDE에서 L2 어댑터 도착 보고

Interface:Realtek 8832CU Wireless LAN WiFi 6 USB NIC

Interface GUID: b668ac45-c78e-443b-8549-05fdbfd76294

Connection Mode:프로필에 자동 연결

Profile:시냅스이미징

SSID:시냅스이미징

BSS Type:Infrastructure

Session Duration: 25 hours 39 minutes 34 seconds

Disconnect Reason:드라이버에 의해 네트워크 연결이 끊어졌습니다.

EventId	Time	Message
8000	2026-06-06T10:04:18	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-06T10:04:18	[+]무선 네트워크 연결을 시작했습니다.
11001	2026-06-06T10:04:19	[+]무선 네트워크 연결이 성공했습니다.
11010	2026-06-06T10:04:19	[+]무선 보안을 시작했습니다.
11005	2026-06-06T10:04:19	[+]무선 보안에 성공했습니다.
8001	2026-06-06T10:04:19	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
11004	2026-06-06T10:04:19	[+]무선 보안이 중지되었습니다.
1010	2026-06-06T10:04:19	[+]CDE에서 L2 어댑터 제거 보고
10000	2026-06-06T10:04:23	[+]WLAN 확장성 모듈을 시작하지 못했습니다.
1009	2026-06-06T10:04:23	[+]CDE에서 L2 어댑터 도착 보고
8000	2026-06-06T10:04:28	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-06T10:04:28	[+]무선 네트워크 연결을 시작했습니다.

11001	2026-06-06T10:04:28	[+]무선 네트워크 연결이 성공했습니다.
11010	2026-06-06T10:04:28	[+]무선 보안을 시작했습니다.
11005	2026-06-06T10:04:28	[+]무선 보안에 성공했습니다.
8001	2026-06-06T10:04:28	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
4042	2026-06-06T10:04:34	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
11004	2026-06-07T11:43:53	[+]무선 보안이 중지되었습니다.
8003	2026-06-07T11:43:53	[+]WLAN AutoConfig 서비스가 무선 네트워크에서 연결이 끊어졌습니다.

EventId	Time	Message
1010	2026-06-07T11:43:53	[+]CDE에서 L2 어댑터 제거 보고
10000	2026-06-07T11:44:31	[+]WLAN 확장성 모듈을 시작하지 못했습니다.
1009	2026-06-07T11:44:31	[+]CDE에서 L2 어댑터 도착 보고

EventId	Time	Message
4042	2026-06-07T11:43:53	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...

Interface:Realtek 8832CU Wireless LAN WiFi 6 USB NIC
Interface GUID: b668ac45-c78e-443b-8549-05fdbfd76294
Connection Mode:프로필에 자동 연결
Profile:시냅스이미징
SSID:시냅스이미징
BSS Type:Infrastructure
Session Duration: 0 hours 0 minutes 1 seconds
Disconnect Reason:드라이버에 의해 네트워크 연결이 끊어졌습니다.

EventId	Time	Message
8000	2026-06-07T11:44:35	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-07T11:44:35	[+]무선 네트워크 연결을 시작했습니다.
11001	2026-06-07T11:44:35	[+]무선 네트워크 연결이 성공했습니다.
11010	2026-06-07T11:44:35	[+]무선 보안을 시작했습니다.
11005	2026-06-07T11:44:35	[+]무선 보안에 성공했습니다.
8001	2026-06-07T11:44:35	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
11004	2026-06-07T11:44:36	[+]무선 보안이 중지되었습니다.
8003	2026-06-07T11:44:36	[+]WLAN AutoConfig 서비스가 무선 네트워크에서 연결이 끊어졌습니다.

EventId	Time	Message
1010	2026-06-07T11:44:36	[+]CDE에서 L2 어댑터 제거 보고
10000	2026-06-07T11:44:39	[+]WLAN 확장성 모듈을 시작하지 못했습니다.
1009	2026-06-07T11:44:39	[+]CDE에서 L2 어댑터 도착 보고

Interface:Realtek 8832CU Wireless LAN WiFi 6 USB NIC
Interface GUID: b668ac45-c78e-443b-8549-05fdbfd76294
Connection Mode:프로필에 자동 연결
Profile:시냅스이미징
SSID:시냅스이미징
BSS Type:Infrastructure
Session Duration: 22 hours 5 minutes 32 seconds
Disconnect Reason:드라이버에 의해 네트워크 연결이 끊어졌습니다.

EventId	Time	Message
8000	2026-06-07T11:44:43	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-07T11:44:43	[+]무선 네트워크 연결을 시작했습니다.
11001	2026-06-07T11:44:43	[+]무선 네트워크 연결이 성공했습니다.

11010	2026-06-07T11:44:43	[+]무선 보안을 시작했습니다.
11005	2026-06-07T11:44:43	[+]무선 보안에 성공했습니다.
8001	2026-06-07T11:44:43	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
4042	2026-06-07T11:44:48	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
11004	2026-06-08T09:50:14	[+]무선 보안이 중지되었습니다.
8003	2026-06-08T09:50:14	[+]WLAN AutoConfig 서비스가 무선 네트워크에서 연결이 끊어졌습니다.

EventId	Time	Message
4042	2026-06-08T09:50:15	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
10001	2026-06-08T09:50:16	[+]WLAN 확장성 모듈을 시작했습니다.

Interface:Realtek 8832CU Wireless LAN WiFi 6 USB NIC
Interface GUID: b668ac45-c78e-443b-8549-05fdbfd76294
Connection Mode:프로필에 자동 연결
Profile:시냅스이미징
SSID:시냅스이미징
BSS Type:Infrastructure
Session Duration: 3 hours 28 minutes 28 seconds
Disconnect Reason:Unknown

EventId	Time	Message
8000	2026-06-08T09:50:20	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-08T09:50:20	[+]무선 네트워크 연결을 시작했습니다.
11001	2026-06-08T09:50:21	[+]무선 네트워크 연결이 성공했습니다.
11010	2026-06-08T09:50:21	[+]무선 보안을 시작했습니다.
11005	2026-06-08T09:50:21	[+]무선 보안에 성공했습니다.
8001	2026-06-08T09:50:21	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
4042	2026-06-08T09:50:26	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
4042	2026-06-08T09:50:31	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
11004	2026-06-08T09:50:31	[+]무선 보안이 중지되었습니다.
10002	2026-06-08T09:50:31	[+]WLAN 확장성 모듈을 중지했습니다.
4001	2026-06-08T09:50:31	[+]WLAN AutoConfig 서비스를 중지했습니다.
12	2026-06-08T09:50:47	[+]운영 체제가 시스템 시간 2026-06-08T00:50:47.500000000Z에 시작되었습니다.
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
1009	2026-06-08T09:51:06	[+]CDE에서 L2 어댑터 도착 보고
4000	2026-06-08T09:51:07	[+]WLAN AutoConfig 서비스를 시작했습니다.
10001	2026-06-08T09:51:07	[+]WLAN 확장성 모듈을 시작했습니다.
1009	2026-06-08T09:51:07	[+]CDE에서 L2 어댑터 도착 보고
1015	2026-06-08T09:51:07	[+]인터페이스 토큰 적용
8000	2026-06-08T09:51:09	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-08T09:51:09	[+]무선 네트워크 연결을 시작했습니다.
11001	2026-06-08T09:51:09	[+]무선 네트워크 연결이 성공했습니다.
11010	2026-06-08T09:51:09	[+]무선 보안을 시작했습니다.
11005	2026-06-08T09:51:09	[+]무선 보안에 성공했습니다.
8001	2026-06-08T09:51:09	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
4042	2026-06-08T09:51:13	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
11004	2026-06-08T13:13:47	[+]무선 보안이 중지되었습니다.

10002	2026-06-08T13:13:47	[+]WLAN 확장성 모듈을 중지했습니다.
1010	2026-06-08T13:13:47	[+]CDE에서 L2 어댑터 제거 보고
4042	2026-06-08T13:13:48	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...
10001	2026-06-08T13:13:48	[+]WLAN 확장성 모듈을 시작했습니다.
1009	2026-06-08T13:13:48	[+]CDE에서 L2 어댑터 도착 보고
8000	2026-06-08T13:13:52	[+]WLAN AutoConfig 서비스가 무선 네트워크에 대한 연결을 시작했습니다.
11000	2026-06-08T13:13:52	[+]무선 네트워크 연결을 시작했습니다.
11001	2026-06-08T13:13:53	[+]무선 네트워크 연결이 성공했습니다.
11010	2026-06-08T13:13:53	[+]무선 보안을 시작했습니다.
11005	2026-06-08T13:13:53	[+]무선 보안에 성공했습니다.
8001	2026-06-08T13:13:53	[+]WLAN AutoConfig 서비스가 무선 네트워크에 연결되었습니다.
4042	2026-06-08T13:13:58	[+]{b668ac45-c78e-443b-8549-05fdbfd76294}에서 기능 변경(0x47008003000000 제품군: V4 기능...